







# 3ЭЦВ 6-4





# 3ЭЦВ 6-6,5





# 3ЭЦВ 6-10





### ЗЭЦВ 6-16





### 3ЭЦВ 6-25





### 3ЭЦВ 6-25



# ЗЭЦВ 8-16





# 3ЭЦВ 8-25









### 3ЭЦВ 8-40





# 3ЭЦВ 8-65



# 3ЭЦВ 10-65




# ЗЭЦВ 10-120




# 3ЭЦВ 10-160



H, м





$\eta$ , %





# 3ЭЦВ 10-200



# 3ЭЦВ 12-160





# 3ЭЦВ 12-200





# 3ЭЦВ 12-210



# ЗЭЦВ 12-250

